



# COMMON CRITERIA MAINTENANCE REPORT

SecureSwitch® Fiber Optic Switch, Models: 1:1, 2:1, 3:1, 4:1, 5:1,  
6:1,7:1 and 8:1

383-7-152

February 20, 2018

V 1.0





# FOREWORD

This Maintenance Report is an UNCLASSIFIED publication, issued under the authority of the Chief, Communications Security Establishment (CSE). Suggestions for amendments should be forwarded through departmental communications security channels to your Client Services Representative at CSE.

If your department has identified a requirement for report based on business needs and would like more detailed information, please contact:

ITS Client Services

Telephone: (613) 991-7654

E-mail: [itsclientservices@cse-cst.gc.ca](mailto:itsclientservices@cse-cst.gc.ca)



# OVERVIEW

Market Central, Inc. has submitted the Impact Analysis Report (IAR) for SecureSwitch® Fiber Optic Switch, Models: 1:1, 2:1, 3:1, 4:1, 5:1, 6:1,7:1 and 8:1 (hereafter referred to the TOE), satisfying the requirements outlined in Assurance Continuity: CCRA Requirements, v2.1, June 2012. In accordance with those requirements, the IAR describes the changes implemented in the TOE, (the maintained Target of Evaluation), the evidence updated as a result of the changes and the security impact of the changes.



# TABLE OF CONTENTS

<b>1</b>	<b>Changes</b> .....	<b>5</b>
1.1	Description of changes in the Maintained Target of Evaluation .....	5
1.2	Affected developer evidence.....	5
1.3	Conclusions.....	5
1.4	References .....	6



# 1 CHANGES

The following characterizes the changes implemented in the TOE and/or the environment. For each change, it was verified that there were no required changes to the security functional requirements in the ST, and thorough functional and regression testing was conducted by the developer to ensure that the assurance in the Target of Evaluation (TOE) was maintained.

## 1.1 DESCRIPTION OF CHANGES IN THE MAINTAINED TARGET OF EVALUATION

The changes in the TOE comprise;

- Adding new platforms by changing the ST connectors for duplex LC fiber optic connectors.

## 1.2 AFFECTED DEVELOPER EVIDENCE

Modifications to the product necessitated changes to a subset of the developer evidence that was previously submitted for the TOE. The set of affected developer evidence was identified in the IAR.

- Modifications to the security target were made to reflect the new part numbers.

## 1.3 CONCLUSIONS

Through functional and regression testing of the TOE, assurance gained in the original TOE certification was maintained. As all of the changes to the maintained TOE have been classified as minor, it is the conclusion of the CB that the maintained TOE is appropriate for assurance continuity and re-evaluation is not required.

The IT product identified in this report has been previously evaluated at an approved evaluation facility established under the Canadian Common Criteria Evaluation and Certification Scheme using the Common Methodology for IT Security Evaluation, Version 3.1 Revision 4, for conformance to the Common Criteria for IT Security Evaluation, Version 3.1 Revision 4.

This is not an endorsement of the IT product by CSE or by any other organization that recognizes or gives effect to this certificate, and no warranty of the IT product by CSE or by any other organization that recognizes or gives effect to this certificate, is expressed or implied.



## 1.4 REFERENCES

---

Reference
Assurance Continuity: CCRA Requirements, v2.1, June 2012
Certification Report SecureSwitch® Fiber Optic Switch Models: 1:1, 2:1, 3:1, 4:1, 5:1, 6:1,7:1 and 8:1Rev A, 12 October, 2016, version 1.0
SecureSwitch® Fiber Optic Switch Models: 1:1, 2:1, 3:1, 4:1, 5:1, 6:1,7:1 and 8:1 Security Target, July 2016, version 1.1