

Samsung SCX-5737FW/SCX-5739FW Control  
Software V2.00.03.02

---

Samsung Electronics Co., Ltd.

**Certificate Effectiveness Maintenance Report**

**Certification No : KECS-CISS-0379-2012**

**July 2013**



IT Security Certification Center

## **1. TOE**

Samsung SCX-5737FW/SCX-5739FW Control Software V2.00.03.02

## **2. Date of Application**

28 January 2013

## **3. Date of Activity**

5 July 2013

## **4. Overview**

The Target of Evaluation (TOE) is an embedded software product for MFPs (Multi-Function Peripherals) as an IT product. It controls the operation of the entire MFP, including copy, print, scan, and fax functions on the MFP controller.

The change to the certified product has no effect on assurance. Therefore, the assurance as outlined in the Certification Report KECS-CISS-0379-2012 is maintained for this version of the product.

This report is an addendum to Certification Report KECS-CISS-0379-2012.

## **5. Changes to TOE**

The changes to the product were firmware bug fixes to SNMP setting

## 6. Assessment

The vendor for Samsung SCX-5737FW/SCX-5739FW Control Software V2.00.03.02 submitted IAR [2] to IT Security Certification Center for approval. The IAR is intended to satisfy the requirements outlined in the document Assurance Continuity [1]. The IAR includes the following items;

- A. The changes made to the certified TOE
- B. The evidence updated as a result of the changes and,
- C. The security impact of the changes

The vendor changed only two abbreviation terms. The security target[3] is correctly updated.

## 7. Conclusion

The change to the TOE is to hardware models. Consideration of the nature of the change leads to the conclusion that it is classified as a minor change and that certificate maintenance is the correct path to continuity of assurance.

Therefore, IT Security Certification Center agrees that the assurance as outlined in the Certification Report [4] is maintained for this version of the product.

## 8. References

- [1] Common Criteria document “Assurance Continuity: CCRA Requirements”, version 2.1, June 2012
- [2] “Samsung SCX-5737FW/SCX-5739FW Control Software V2.00.03.02 Security Impact Analysis Report ”, V1.0, June 11, 2013
- [3] Samsung SCX-5737FW/SCX-5739FW Control Software V2.00.03.02 Security Target v1.3, January 10, 2013
- [4] Certification Report, Samsung SCX-5737FW/SCX-5739FW Control Software V2.00.03.00 (KECS-CISS-0365-2012)”, March 2012