



## CCEVS APPROVED ASSURANCE CONTINUITY MAINTENANCE REPORT

### ASSURANCE CONTINUITY MAINTENANCE REPORT FOR

**Xerox WorkCentre/WorkCentre Pro 232/238/245/255/265/275 Multifunction Systems, running system software version 12.039.24.001  
(see last section below for complete listing of the software/firmware in the evaluated configuration).**

**Maintenance Report Number: CCEVS-VR-06-0021a**

**Date of Activity:** 23 August 2006

**References:** Common Criteria document CCIMB-2004-02-009 "Assurance Continuity: CCRA Requirements", version 1.0, February 2004;

"Xerox WorkCentre/WorkCentre Pro 232/238/245/255/265/275 Impact Analysis Review", 05 July 2006

**Documentation Updated:** Xerox WorkCentre/WorkCentre Pro 232/238/245/255/265/275 developer evidence documents.

#### **Assurance Continuity Maintenance Report:**

The vendor for the WorkCentre/WorkCentre Pro 232/238/245/255/265/275 Multifunction Systems, Xerox Corporation, submitted an Impact Analysis Report (IAR) to CCEVS for approval on 07 July 2006. The IAR is intended to satisfy requirements outlined in Common Criteria document CCIMB-2004-02-009, "Assurance Continuity: CCRA Requirements", version 1.0, February 2004. In accordance with those requirements, the IAR describes the changes made to the certified TOE, the evidence updated as a result of the changes and the security impact of the changes.

#### **Changes to TOE:**

The updated software release makes minor bug fixes to both the TOE Network Controller subsystem software and the Copy Controller subsystem software.

#### **Conclusion:**

CCEVS has determined that none of these changes is security-relevant, and none affect the previously submitted development evidence. Each change has been accompanied by the full SPAR (System Problem Action Request) listing showing what files were changed and what additional testing was performed by Xerox.

The non-security relevance of the set of changes leads to the conclusion that it is classified as a minor change and that certificate maintenance is the correct path to continuity of assurance. Therefore, CCEVS agrees that the original assurance is maintained for the above-cited versions of the product.

#### **Maintained version of the TOE:**

## CCEVS APPROVED ASSURANCE CONTINUITY MAINTENANCE REPORT

The versions of the TOE are identified by the collection of the software/firmware running on them. The versions of the TOE covered by this maintenance action are:

<b>Software/Firmware Item</b>	<b>WorkCentre</b>	<b>WorkCentre + PostScript</b>	<b>WorkCentre Pro</b>
System Software	<b>12.039.24.001</b>	<b>14.039.24.001</b>	<b>13.039.24.001</b>
Network Controller Software	<b>040.010.01123</b>	<b>040.010.11123</b>	<b>040.010.51123</b>
UI Software	<b>012.39.026</b>	<b>012.39.026</b>	<b>012.39.026</b>
IOT Software	<b>61.40.00</b>	<b>61.40.00</b>	<b>61.40.00</b>
SIP Software	<b>12.39.04</b>	<b>12.39.04</b>	<b>12.39.04</b>
DADH Software	<b>14.00.00</b>	<b>14.00.00</b>	<b>14.00.00</b>
FAX Software	<b>02.27.11</b>	<b>02.27.11</b>	<b>02.27.11</b>
Finisher Software (Options)			
• 1K LCSS	<b>01.27.00</b>	<b>01.27.00</b>	<b>01.27.00</b>
• 2K LCSS	<b>03.20.00</b>	<b>03.20.00</b>	<b>03.20.00</b>
• HCSS	<b>13.38.00</b>	<b>13.38.00</b>	<b>13.38.00</b>
• HCSS with BookletMaker	<b>24.10.00</b>	<b>24.10.00</b>	<b>24.10.00</b>
Scanner Software (Options)			
• 232/238/245/255 PPM Models	<b>17.05.00</b>	<b>17.05.00</b>	<b>17.05.00</b>
• 265/275 PPM Models	<b>04.09.00</b>	<b>04.09.00</b>	<b>04.09.00</b>